

KLINGE CORPORATION



SERVICE BULLETIN

Subject: Scrambled segments on temperature displays	Bulletin No: 20121227
	Issued: 12/27/2012

EFFECTIVITY

This Bulletin will address Klinge systems containing temperature displays manufactured between March 5 and September 6, 2012, with display serial number 12061-XXX.

DESCRIPTION

The temperature displays used on Klinge systems (part number K31 00811 00) contain a filter designed to remove noise to ensure the correct characters are shown. Systems manufactured in 2012 contained a filter that may not be able to remove all noise, thus showing scrambled segments on the display. If this happens, the system will continue to operate properly, however the operating temperature of the system may not be able to be read.

ACTION REQUIRED

A new display filter has been developed and is available from Klinge. If you have experienced display problems, please contact someone from the Klinge Sales Team.